

## COWLITZ COUNTY

### SITE I

### Reynolds Metals Aluminum Smelter

CleanupSite ID: **11796**

FS ID: **29**

Alternate Name(s): CHINOOK VENTURES INC LONGVIEW, LONGVIEW ALUMINUM LLC, Millennium Bulk Terminals Longview, Reynolds Metals Aluminum Smelter, REYNOLDS METALS CO, REYNOLDS METALS CO LONGVIEW, REYNOLDS METALS CO LONGVIEW REDUCTION PL, REYNOLDS METALS PCB

### LOCATION:

[View Vicinity Map](#)

Address: **4029 INDUSTRIAL WAY**  
**LONGVIEW 98632**

Lat/Long: **46.14146 -122.99635**  
Township/Range/Section: **8N 3W 38**

Legislative District: **19**  
Congressional District: **3**

### STATUS:

[View Site Web Page](#)

Ecology Status: **Cleanup Started**  
WARM BIN#: **5**

Responsible Unit: **Industrial**  
Site Manager: **Skyllingstad, Paul**  
Statute: **MTCA**

Is Brownfield?  
Environmental Covenant?  
Is PSI Site?

UST Site ID: **11040**  
WRIA ID: **25**

NFA Received? NFA Date: NFA Reason:

### ASSOCIATED CLEANUP UNIT(s)

culD	Cleanup Unit Name	Unit Type	Process Type	Unit Status	Size (Acres)	ERTS ID
22	LONGVIEW ALUMINUM LLC	Upland	Ecology-supervised or conducted	No Further Action Required		
7024	LONGVIEW ALUMINUM LLC	Upland	Independent Action	Awaiting Cleanup		
12392	Reynolds Metals Aluminum Smelter	Upland	Ecology-supervised or conducted	Cleanup Started		
23	REYNOLDS METALS CO LONGVIEW REDUCTION PL	Upland	Independent Action	Cleanup Complete - Active O&M/Monitoring ongoing		

### SITE ACTIVITIES:

Applies to:	Related ID (Unit-LUST-VCP)	Activity Display Name	Status	Start Date	End Date	Legal Mechanism	Performed By	Project Manager
CleanupSite		Site Discovery/Release Report Received			1/2/1989			Skyllingstad, Paul
CleanupSite		Initial Investigation / Federal Preliminary Assessment	Completed	3/1/1989	4/29/1989		Ecology	Skyllingstad, Paul
CleanupSite		Site Hazard Assessment/Federal Site Inspection	Completed	9/1/1990	12/1/1990		Ecology	Skyllingstad, Paul
CleanupSite		Hazardous Sites Listing/NPL			2/5/1991			Skyllingstad, Paul
CleanupSite MilestoneType		Ecology Remedial Investigation and/or Feasibility Study	Completed	6/1/2006	6/1/2009	Agreed Order	PLP	Skyllingstad, Paul

CleanupSite MilestoneType		Ecology Remedial Investigation and/or Feasibility Study	Completed	3/1/2007	4/1/2009	Agreed Order	PLP	Skyllingstad, Paul
CleanupUnit	23	Independent Report Review - Unpaid	Completed	1/2/1989	10/24/1989	Independent	Ecology	Skyllingstad, Paul
Lust	6014	LUST - Notification		11/5/2004	11/5/2004			Johnston, Carol
Lust	6014	LUST - Site Assessment Report			6/18/2004			

## AFFECTED MEDIA & CONTAMINANTS:

### Media:

Contaminant:	Ground Water	Surface Water	Soil	Sediment	Air	Bedrock
Conventional Contaminants, Inorganic	C		R			
Conventional Contaminants, Organic			C			
Metals - Other	C		C			
Petroleum Products-Unspecified			C			
Petroleum-Diesel			RB			
Petroleum-Other	C		C			
Polychlorinated biPhenyls (PCB)		R	R			
Polynuclear Aromatic Hydrocarbons	C		C			

### Key:

B - Below Cleanup Level  
C - Confirmed Above Cleanup Level  
S - Suspected

R - Remediated  
RA - Remediated-Above  
RB - Remediated-Below